

Original post set 1820 by Wm. B. Laughlin with witness: 8" ash S 37 E; 18" elm N 50 W 14 links N of the northwest corner of Sec. 19-17-4 per Marion County Atlas pg. 8. No recorded survey entries were found for this section corner per Washington Township Legal Survey Book. Burres 10-1-48 called bronze plug as the corner. 1-29-76 Wilcoxen reports an iron pin, but Wilcoxen 3-7-83 recovered a brass plug from 2 references of 1948. Brass plug found 0.50' S and 0.10' W of iron pin per previously tie. Gries 10-3-86 set Harrison per street plans from Sebree, Craig & McKneight. The location of the corner from the mentioned street plans were found to be in error. Corner & NWQ 19-17-4 were re-set 5-26-88. Corner corrected 1.60'E and 1.12'N of its location by street plans. Re-tied 3-20-99 by Wilcoxen. Re-tied 5-18-05 by Wilcoxen.

REF.	DISTANCE	DESCRIPTION
1.	52.01	Cut 'x' W-end of concrete headwall
2.	9.20'	Due S to NW corner of 19-17-4 (Harrison)
3.	33.31'	N face of steel fence post
4.	20.55	Cut 'x' SW rim of sewer manhole
5.	59.00'	PK nail N PwP#321-259B 36"up
	l	